

ALPHONSE ASSOCIATES
ARCHITECTS AND INTERIOR DESIGNERS
No. 47, Sri Krupa, Bannimantap Extn.,
Mysore – 570 015. Ph. : 2495832

Adithya Varma
B.Arch. F.I.I.A.
ARCHITECT
Reg. No CA / 2011 / 53589

Ref. No AA-JS-001

Date : 13-04-2024

TO WHOM SO EVER IT MAY CONCERN

STABILITY CERTIFICATE

I hereby certify that the existing St. Joseph's School building at Jayalakshmipuram, Mysore is structurally stable and the foundation was designed according to I.S loading standards 875 and other Indian Standard Code of practice and do here by declare that the building is structurally sound and the building can function as usual.

The certificate is valid for one year from the date of issue and it will be renewed before the expiry of the stipulated period.

Thanking you.

**Yours sincerely,
(For Alphonse Associates)**



Adithya Varma
(Architect)

ALPHONSE ASSOCIATES
Architech And Interior Designers
No: 47, Srikrupa, 2nd Main,
Bannimantap 'A' Layout,
Mysore - 15.

ಕರ್ನಾಟಕ ಸರ್ಕಾರ



ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಬಂದರು ಮತ್ತು ಒಳನಾಡು ಜಲಸಾರಿಗೆ ಇಲಾಖೆ,
ಗುಣಭರವಸೆ ವಿಭಾಗ, ಮೈಸೂರು.

ಸಂ:ಕಾ.ಇಂ:ಲೋ.ಇ:ಗುಭ:ವಿ:ಮೈ:ದೃಡೀಕರಣ:2016-17/520.

ದಿನಾಂಕ: 29.11.16.

ಇವರಿಗೆ,

ಪ್ರಾಂಶುಪಾಲರು,
ಸೆಂಟ್ ಜೋಸೆಫ್ ಶಾಲೆ,
IV ಬ್ಲಾಕ್, ಟೆಂಪಲ್ ರೋಡ್,
ಜಯಲಕ್ಷ್ಮಿ ಪುರಂ, ಮೈಸೂರು.

ಮಾನ್ಯರೇ,

ವಿಷಯ:- ಮೈಸೂರಿನ ಸೆಂಟ್ ಜೋಸೆಫ್ ಶಾಲೆಯ ಕಟ್ಟಡದ ದೃಡೀಕರಣ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ:- 1. ಪ್ರಾಂಶುಪಾಲರು, ಸೆಂಟ್ ಜೋಸೆಫ್ ಶಾಲೆ, ಮೈಸೂರು ರವರ ಪತ್ರ ದಿನಾಂಕ: 19.11.2016

2. ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋ.ಇ, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ: 1191, ದಿನಾಂಕ:29.11.2016.

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖ ಪತ್ರ(1) ರ ಅನ್ವಯ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು, ದಿನಾಂಕ:24.11.2016 ರಂದು ಸ್ಥಳ ಪರಿಶೀಲನೆ ಮಾಡಿ ಹಾಗೂ ಕಟ್ಟಡದ ದೃಡೀಕರಣಕ್ಕಾಗಿ ರೂ.5000/- ಗಳನ್ನು ರಶೀದಿ ಸಂಖ್ಯೆ: 0289417, ದಿನಾಂಕ: 28.11.2016 ರಂದು ಪಾವತಿ ಮಾಡಿಸಿಕೊಂಡಿರುವ ಬಗ್ಗೆ ಉಲ್ಲೇಖ ಪತ್ರ(2) ರಲ್ಲಿ ತಿಳಿಸಿರುತ್ತಾರೆ.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಗುಣಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಉಲ್ಲೇಖ ಪತ್ರ(2) ರಲ್ಲಿ ಸದರಿ ಕಟ್ಟಡಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುವ ಪೂರಕ ವರದಿಯನ್ನು ಈ ಪತ್ರದೊಂದಿಗೆ ಲಗತ್ತಿಸಿ ಸಲ್ಲಿಸಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ:

ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋ.ಇ. ಗುಣಭರವಸೆ ವಿಭಾಗ,
ಮೈಸೂರು.



"TRUE COPY"
Compared with the Original
and Found Correct

NOTARY MYSORE

1 DEC 2016

GOVERNMENT OF KARNATAKA
Executive Engineer, Public Works Ports and Inland Water Transport Department
Quality Assurance Division, Mysore

No.EE.PWD/QAD,Mys/certi./2016-17 /520

Date:29/11/2016

To
Principal
St.Joseph's School,
4th Block, Temple Road,
Jayalakshampuram, Mysore.

Sir,

Sub: Certification of school building St.Joseph's School, Mysore -reg.

Ref: 1) Principal St.Joseph's School, Mysore their letter dated 19/11/2016.
2) Executive Engineer, Public Works Department, Quality Assurance
Division,

Mysore their letter No.1191, dated 29/11/2016.

Concerned to the subject above as per ref (1) Assistant Executive Engineer, Quality Assurance Division, Mysore on date 24/11/2016 having done spot verification and for building certification having got the Rs.5,000/- vide receipt No.0289417, dated 28/11/2016 towards remittance in ref (2) has informed.

Assistant Executive Engineer, Quality Assurance Division, Mysore as per ref (2) letter has submitted complete report concerned to the building, submitted herewith to the office is enclosed.

Yours faithfully,

Sd/

Executive Engineer, Public Works Dept.
Quality Assurance Division, Mysore

Patil

Kannada text translated into English


By D. Jayalakshmi A Patil

TRANSLATED this document from the
original in.....Kannada.....language to
English and the translation Verified by me

Umesh

NOTARY, MYSORE

[Signature]
दक्षिण क्षेत्रीय भाषा केंद्र
Southern Regional Language Centre
मानसगंगा, मैसूर-570006
Manasaganqotri Mysuru-570006



1 DEC 2016


Office of Executive Engineer
Quality Assurance Division
PW, P&IWT Department
Phone:

TO WHOM SO EVER IT MAY CONCERN

Ref: 1. Principal St. Joseph's School, Jayalakshmipuram, Mysuru. Letter
Dated: 19-11-2016.

2. Assistant Executive Engineer, P.W.P & I.W.T. Dept, Quality Assurance
Subdivision, Mysore office No-1191, Dated: 29-11-2016.

On the above cited request, The school building located and
Jayalakshmipuram, Mysuru. In inspected on 24/11/2016 and found that the
building comprises of three blocks i.e C, D & F blocks. "C" Blocks comprises
of ground, 1st and 2nd Floor, of each 2342 sq.mtr plinth area. "E" Blocks
comprises of ground, 1st and 2nd Floor of each 1175 sq.mtr plinth area., and "E"
Comprise basement floor, Ground, 1st & 2nd Floor of each 1575 sq.mtr plinth
area.,



The structure is constructed as R.C.C. formed structure with brick &
block masonry, flush doors, steel windows & tiled flooring.

On the day of inspection the structure has found no foundation
settlements, structural cracks, masonry cracks. The ventilation for the
classrooms, electrical works, water supply works & sanitation works found

TRUE COPY

checked with the Original
and Found Correct

[Handwritten signature]

NOTARY MYSORE,

1 DEC 2016

functioning satisfactory and each block has separate strain cases. Regarding building stability Alphonse associates, Mysuru given stability certificate on 08-07-2015.

Based on the above facts it is found that the building is structurally safe for the school purpose, provided that the routine and annual maintenance of the building should be carried out periodically by professional service providers under the supervision of engineer.

Executive Engineer
Quality Assurance Division,
Mysuru.

Copy to:

- The Principal, St. Joseph's School 75, IV Block, Temple Road, Jayalakshmipuram, Mysuru-570012.



"TRUE COPY"
Compared with the Original
and Found Correct

Vasudeva
NOTARY MYSORE

1 DEC 2016